



INTRODUCTION

Technological development in the electronic field has transformed power electronics from static conversion technology to its essential element in the electrical and electronic area. Its aim is the power flow control through the voltage conversion from mains by power semiconductors capable to perform switching, control and convert electrical energy functions efficiently and reliably.

On the last years, there have been significant improvements on this technology sector.

Results achieved on the microelectronics field have allowed the use of linear circuits with integrated components such as controllers on power electronics systems.

The new production techniques have improved components voltage and current characteristics and increased their switching speed.

Furthermore, computers development, communication systems and commercial electronics products, on the need for a better use of the available energy, have led to an increase stable power supply requirement. As a particular interest is the use of power electronics on a DC and three-phase motors at constant and variable speed control.

All of this fits into a wide and reliable applications on many sectors, from residential (cooling systems, air conditioning, kitchen lighting), to commercial (similar to residential, but with additional office equipment and a computer, continuity group, elevators), from industrial (pumps, compressors, fans, robots, welding systems, industrial laser) to an absolutely important area, transportation (electric train, battery loaders, tram, metro, car); from telecommunications (power supply and battery loaders) to space technology (power supply systems on satellites and aircrafts).

De Lorenzo has designed a laboratory on power electronics study, which allows students a practical learning based on a practical implementation of guided exercises. All components that make up the laboratory are industrial used, mounted on didactic panels for a proper handling; all of this enables the laboratory to be used for educational purposes, as well as, design, development and research, thanks to its modular qualities.

Starting from basic principles, with the aid of high-training manuals, the student follows a didactic path into a gradual study of complex circuits.







ALTERNATE CURRENT - DIRECT CURRENT CONVERSION

In most of the applications of power electronics, the input power is in the form of a sinusoidal wave coming from the mains network which is then converted to direct current.

In many cases, the conversion is of the non-controlled type, with the use of diode rectifiers.

However, in some applications, such as, for example, some types of drives of ac and dc motors, it is necessary that the dc output voltage be controllable.

In this case, thyristor converters for the mains frequency phase control are used. They are utilized in particular in high voltage dc power transmission or in all those applications where it is necessary to control the power flow in both directions between the dc side and the ac side.

This trainer have a modular structure and it consists of didactic panels installed on a vertical frame. It is supplied with a theoretical and practical manual. The modularity of these didactic system grants to the students a direct and immediate approach to the topics, offering the opportunity to study various subjects performing several experiments as following:

DCA 201.1 DIODES AND UNCONTROLLED RECTIFIERS

Uncontrolled diodes

- Selenium diode
- Silicon diode

Uncontrolled static converter circuits

- Single pulse rectifier E1UK, ohmic load
- Single pulse rectifier E1UK, ohmic-inductive load
- Two-pulse rectifier M2UK, ohmic load
- Two-pulse rectifier M2UK, ohmic-inductive load
- Two-pulse bridge rectifier B2UK, ohmic load
- Two-pulse bridge rectifier B2UK, ohmic-inductive load
- Three-pulse rectifier M3UK, ohmic load
- Three-pulse rectifier M3UK, ohmic-inductive load
- Six-pulse rectifier M6UK, ohmic load
- Six-pulse rectifier M6UK, ohmic-inductive load
- Six-pulse bridge rectifier B6UK, ohmic load
- Six-pulse bridge rectifier B6UK, ohmic-inductive load





DCA 201.2 SCR AND CONTROLLED RECTIFIERS

Thyristors

SCR

Single pulse converters

- Single pulse converter E1CK, ohmic load
- Single pulse converter E1CK, inductive load
- Single pulse converter E1CK, ohmic-inductive load
- Single pulse converter E1CK, ohmic-inductive load and free-wheeling diode
- Single pulse converter E1CK, ohmic-inductive load and back e.m.f.
- Single pulse rectifier E1UK, ohmic-capacitive load
- Single pulse converter E1CK, ohmic-capacitive load

Two-pulse midpoint converters

- Two-pulse midpoint converter M2CK, ohmic load
- Two-pulse midpoint converter M2CK, ohmic-inductive load

Multi-phase converters

- Three-pulse midpoint converter M3CK, ohmic load
- Three-pulse midpoint converter M3CK, ohmic-inductive load
- Six-pulse midpoint converter M6CK, ohmic load
- Six-pulse midpoint converter M6CK, ohmic-inductive load

Drainage-coil converters

• Double three-pulse star converter M3CK2, ohmic load

Bridge converters

- Half-controlled bridge B2HK, ohmic load
- Half-controlled bridge B2HK, ohmic-inductive load
- Half-controlled bridge B2HZ, ohmic load
- Half-controlled bridge B2HZ, ohmic-inductive load
- Fully-controlled bridge B2C, ohmic load
- Fully-controlled bridge B2C, ohmic-inductive load
- Fully-controlled bridge B2C, ohmic load and back e.m.f.
- Fully-controlled bridge B2C, dc motor load
- Fully-controlled bridge B2C, ohmic load and supplementary dc voltage
- Fully-controlled bridge B2C, dc generator load
- Three-phase half-controlled bridge B6HK, ohmic load
- Three-phase fully-controlled bridge B6C, ohmic load
- Three-phase fully-controlled bridge B6C, ohmic-inductive load





| Code | Description | DCA 201.1 | DCA 201.2 | Total quantities |
|-------------|---|-----------|-----------|---------------------|
| | | | | |
| DL 2601 | SELENIUM RECTIFIER | 1 | | 1 |
| DL 2602 | SILICON DIODE | 1 | | 1 |
| DL 2603 | GROUP OF DIODES | 1 | 1 | 1 |
| DL 2604 | SCR | | 1 | 1 |
| DL 2605 | GROUP OF SCR | | 1 | 1 |
| DL 2613 | DC POWER SUPPLY | | 1 | 1 |
| DL 2614 | VOLTAGE REFERENCE GENERATOR | | 1 | 1 |
| DL 2615 | TRIGGER POINT LIMITER | | 1 | 1 |
| DL 2616 | TWO PULSE CONTROL UNIT | | 1 | 1 |
| DL 2617 | SIX PULSE CONTROL UNIT | | 1 | 1 |
| DL 2626 | MAINS TRANSFORMER | 1 | 1 | 1 |
| DL 2628 | SUPER-FAST FUSES | 2 | 2 | 2 |
| DL 2635 | LOAD | 1 | 1 | 1 |
| DL 2636 | SOCKETS WITH LAMPS | | 1 | 1 |
| DL 2637 | STABILIZED POWER SUPPLY | | 1 | 1 |
| DL 2643 | SUPPORT WITH 3 SHUNTS 1 OHM | 1 | 1 | 1 |
| DL 2644 | SUPPORT WITH 3 SHUNTS 0,1 OHM | | 1 | 1 |
| DL 12B12 | BATTERY STACK | | 1 | 1 |
| DL 2025DT | TACHOMETER | | 1 | 1 |
| DL 2109D33 | TRUE RMS METER | 2 | 2 | 2 |
| DL 2109T3PV | MOVING IRON VOLTMETER | 1 | 1 | 1 |
| DL 2109T2A5 | MOVING IRON AMMETER | 1 | 1 | 1 |
| DL 10200A1 | SHUNT EXCITATION DC MOTOR | | 1 | 1 |
| DL 10250A1 | SHUNT EXCITATION DC GENERATOR | | 1 | 1 |
| DL 10400 | BASE | | 1 | 1 |
| | | | | |
| | For the Countries where the 3-phase mains | | | |
| | supply is different from 380V: | | | |
| DL 2600TTI | THREE PHASE TRANSFORMER | 1 | 1 | 1 |





ALTERNATE CURRENT - ALTERNATE CURRENT CONVERSION

The electrical power in alternate current is controlled by means of thyristors.

The main fields of application of the control of alternate current are in the control of temperature, lighting and induction motors.

The main types of control are: phase control, on-off control and proportional time control.

LIST OF EXPERIMENTS

DCA 202.1 THYRISTORS AND CONTROLLED AC/AC CONVERTERS

Thyristor

TRIAC

Single-phase controllers

- Single-phase ac controller W1C, ohmic load
- Single-phase ac controller W1C, inductive load
- Single-phase ac controller W1C, ohmic-inductive load
- Single-phase ac controller W1, ohmic load
- Single-phase ac controller W1, ohmic-inductive load
- Half-controlled single-phase controller W1H, ohmic load

Three-phase controllers

- Fully controlled three-phase controller W3C, star ohmic load without neutral
- Fully controlled three-phase controller W3H, star ohmic load without neutral
- Three-phase controller W3C2, star ohmic load without neutral

DCA 202.2 LIGHT DIMMER FAULT SIMULATOR

Phase control for the regulation of lighting with fault simulation.

Double time-constant standard light dimmer circuit consisting of triac, diac, two control potentiometers, resistors and capacitors.

20 faults can be switched on using switches located behind a cover. Typical faults: interruptions, short-circuit, faulty components and faulty design.

Examples of exercises:

- Fault-free dimmer
- DIAC shorted
- DIAC with high resistance
- The gate of TRIAC works like a diode
- Control circuit break
- Assembly or component fault
- Trimmer shorted
- Auxiliary RC circuit not included
- Variable resistance R shorted
- TRIAC shorted





| Code | Description | DCA 202.1 | DCA 202.2 | Total quantities |
|-------------|---|-----------|-----------|------------------|
| | | | | |
| DL 2603 | GROUP OF DIODES | 1 | | 1 |
| DL 2605 | GROUP OF SCR | 1 | | 1 |
| DL 2607 | TRIAC | 1 | | 1 |
| DL 2613 | DC POWER SUPPLY | 1 | | 1 |
| DL 2614 | VOLTAGE REFERENCE GENERATOR | 1 | | 1 |
| DL 2616 | TWO PULSE CONTROL UNIT | 1 | | 1 |
| DL 2617 | SIX PULSE CONTROL UNIT | 1 | | 1 |
| DL 2626 | MAINS TRANSFORMER | 1 | 1 | 1 |
| DL 2628 | SUPER-FAST FUSES | 1 | | 1 |
| DL 2635 | LOAD | 1 | | 1 |
| DL 2636 | SOCKETS WITH LAMPS | | 1 | 1 |
| DL 2639 | PHASE CONTROL FAULT SIMULATOR | | 1 | 1 |
| DL 2643 | SUPPORT WITH 3 SHUNTS 1 OHM | 1 | | 1 |
| DL 2109T26 | POWER METER | 1 | | 1 |
| DL 2109D33 | TRUE RMS METER | 2 | | 2 |
| DL 2109T3PV | MOVING IRON VOLTMETER | 1 | | 1 |
| DL 2109T2A5 | MOVING IRON AMMETER | 1 | | 1 |
| DL 2100-3M | FRAME | 2 | 2 | 2 |
| DL 1001-1 | WORKING BENCH | 1 | 1 | 1 |
| DL 1155POW | CONNECTING LEADS | 1 | 1 | 1 |
| | Accessory: | | | |
| DL 2100TA | STORAGE CABINET | 1 | 1 | 1 |
| | For the Countries where the 3-phase mains supply is | | | |
| | different from 380V: | | | |
| DL 2600TTI | THREE PHASE TRANSFORMER | 1 | 1 | 1 |
| | | | | |





DIRECT CURRENT DIRECT CURRENT CONVERSION

Dc - dc converters are widely used in dc power supplies and in some applications of dc motor drive. Often, the input to this type of converters is a dc non-regulated voltage, obtained by rectifying the mains voltage and, consequently, fluctuating due to changes in the amplitude of the line voltage. The result of the conversion is a controlled dc output at the desired voltage level.

LIST OF EXPERIMENTS

DCA 203.1 CHOPPERS

- Main SCR
- MOSFET
- IGBT
- Step-down converter with SCR with turn-off circuit. PWM control.
- Step-down converter with IGBT. PWM control.
- Speed control of a dc motor
- Step-down converter with MOSFET. PWM control.
- Step-down converter with MOSFET. PFM control.
- Step-down converter with MOSFET. TPC control .
- Step-up converter with IGBT. PWM control.
- Step-up converter with IGBT. TPC control.
- Inverting converter with IGBT. PWM control.

DCA 203.2 SWITCHABLE POWER SUPPLY

- Flyback converter with IGBT. PWM control.
- Forward converter with IGBT. PWM control.
- Asymmetric half-bridge forward converter with IGBT. PWM control.





| Code | Description | DCA 203.1 | DCA 203.2 | Total quantities |
|------------|---|-----------|-----------|------------------|
| | | | | |
| DL 2602 | SILICON DIODE | 1 | 4 | 4 |
| DL 2608 | MOSFET | 1 | | 1 |
| DL 2609 | IGBT | 1 | 2 | 2 |
| DL 2611 | BRIDGE THREE PHASE RECTIFIER | 1 | 1 | 1 |
| DL 2612 | SCR WITH TURN OFF CIRCUIT | 1 | | 1 |
| DL 2613 | DC POWER SUPPLY | 1 | 1 | 1 |
| DL 2614 | VOLTAGE REFERENCE GENERATOR | 1 | 1 | 1 |
| DL 2619 | PWM/PFM/TPC CONTROL UNIT | 1 | 1 | 1 |
| DL 2626 | MAINS TRANSFORMER | 1 | 1 | 1 |
| DL 2627 | CAPACITORS | 1 | 1 | 1 |
| DL 2628 | SUPER FAST FUSES | 1 | 1 | 1 |
| DL 2629 | SWITCHING TRANSFORMER | | 1 | 1 |
| DL 2630 | CURRENT TRANSFORMER | 1 | | 1 |
| DL 2635 | LOAD | 1 | 1 | 1 |
| DL 2640 | EMI FILTER | | 1 | 1 |
| DL 2643 | SUPPORT WITH 3 SHUNTS 1 OHM | 1 | 1 | 1 |
| DL 2644 | SUPPORT WITH 3 SHUNTS 0,1 OHM | | 1 | 1 |
| DL 2025DT | TACHOMETER | 1 | | 1 |
| DL 2109D33 | TRUE RMS METER | 2 | 2 | 2 |
| DL 10200A1 | SHUNT EXCITATION DC MOTOR | 1 | | 1 |
| DL 10400 | BASE | 1 | | 1 |
| DL 2100-3M | FRAME | 2 | 2 | 2 |
| DL 1001-1 | WORKING BENCH | 1 | 1 | 1 |
| DL 1155POW | CONNECTING LEADS | 1 | 1 | 1 |
| DI 2100TA | Accessory: | 1 | 4 | 1 |
| DL 2100TA | STORAGE CABINET | 1 | 1 | 1 |
| | For the Countries where the 3-phase mains supply is different | | | |
| DI 2COOTTI | from 380V: | 4 | 4 | 1 |
| DL 2600TTI | THREE PHASE TRANSFORMER | 1 | 1 | 1 |





DIRECT CURRENT ALTERNATE CURRENT CONVERSION

This type of converters are used in ac motor drives and in ac uninterruptible power supplies, where the objective is to supply a sinusoidal ac output with controlled amplitude and frequency. In this section of the laboratory inverters and frequency converters are studied.

LIST OF EXPERIMENTS

DCA 204.1 INVERTERS

- Single-phase full-bridge dc chopper. PWM control.
- Single-phase full-bridge inverter. Square-wave PWM control.
- Single-phase full-bridge inverter. Sinusoidal PWM control.

DCA 204.2 FREQUENCY CONVERTERS

- Frequency converter
- Input controlled rectifier
- Output power inverter

| DL 2610 GROUP OF IGBT DL 2611 BRIDGE THREE PHASE RECTIFIER DL 2613 DC POWER SUPPLY 1 1 1 DL 2614 VOLTAGE REFERENCE GENERATOR DL 2619 PWM/PFM/TPC CONTROL UNIT DL 2625 MATCHING AMPLIFIER 1 1 DL 2626 MAINS TRANSFORMER DL 2626 MAINS TRANSFORMER DL 2627 CAPACITORS 1 1 DL 2638 SUPER FAST FUSES DL 2638 FUNCTION GENERATOR DL 2633 FUNCTION GENERATOR DL 2635 LOAD DL 2637 STABILIZED POWER SUPPLY DL 2640 EMI FILTER DL 2641 SUPPORT WITH 3 SHUNTS 1 OHM DL 2643 SUPPORT WITH 3 SHUNTS 1 OHM DL 2644 SUPPORT WITH 3 SHUNTS 0,1 OHM DL 2646 FREQUENCY CONVERTER DL 21085AL SINGLE PHASE SUPPLY UNIT DL 2109D33 TRUE RMS METER DL 2109D33 TRUE RMS METER DL 2100-3M FRAME DL 2100-3M FRAME DL 2100-3M FRAME DL 2100TA STORAGE CABINET FOR the Countries where the 3-phase mains supply is different from 380V: DL 2600TTI THREE PHASE TRANSFORMER 1 1 1 1 1 1 | Code | Description | DCA 204.1 | DCA 204.2 | Total quantities |
|--|------------|---------------------------|-----------|-----------|------------------|
| DL 2611 BRIDGE THREE PHASE RECTIFIER DL 2613 DC POWER SUPPLY DL 2614 VOLTAGE REFERENCE GENERATOR DL 2619 PWM/PFM/TPC CONTROL UNIT DL 2626 MATCHING AMPLIFIER DL 2626 MAINS TRANSFORMER DL 2627 CAPACITORS DL 2628 SUPER FAST FUSES DL 2633 FUNCTION GENERATOR DL 2633 FUNCTION GENERATOR DL 2635 LOAD DL 2637 STABILIZED POWER SUPPLY DL 2640 EMI FILTER DL 2643 SUPPORT WITH 3 SHUNTS 1 OHM DL 2644 SUPPORT WITH 3 SHUNTS 0,1 OHM DL 2645 FREQUENCY CONVERTER DL 2108SAL SINGLE PHASE SUPPLY UNIT DL 2109D33 TRUE RMS METER DL 2109D34 TRUE RMS METER DL 2100-3M FRAME CONNECTING LEADS ACCESSORY: DL 2100TA STORAGE CABINET FOr the Countries where the 3-phase mains supply is different from 380V: | DI 2640 | CDOUD OF ICET | 4 | | 4 |
| DL 2613 DC POWER SUPPLY 1 | | | _ | | |
| DL 2614 VOLTAGE REFERENCE GENERATOR DL 2619 PWM/PFM/TPC CONTROL UNIT DL 2625 MATCHING AMPLIFIER DL 2626 MAINS TRANSFORMER DL 2627 CAPACITORS 1 | | | | 4 | |
| DL 2619 | | | _ | _ | |
| DL 2625 | | | _ | 1 | |
| DL 2626 | | | | | |
| DL 2627 CAPACITORS 1 1 DL 2628 SUPER FAST FUSES 1 1 DL 2633 FUNCTION GENERATOR 1 1 DL 2635 LOAD 1 1 1 DL 2637 STABILIZED POWER SUPPLY 1 1 1 DL 2640 EMI FILTER 1 1 1 1 DL 2643 SUPPORT WITH 3 SHUNTS 1 OHM 1 | | | | | |
| DL 2628 SUPER FAST FUSES 1 1 DL 2633 FUNCTION GENERATOR 1 1 DL 2635 LOAD 1 1 1 DL 2637 STABILIZED POWER SUPPLY 1 1 1 DL 2640 EMI FILTER 1 1 1 DL 2643 SUPPORT WITH 3 SHUNTS 1 OHM 1 1 1 DL 2644 SUPPORT WITH 3 SHUNTS 0,1 OHM 1 1 1 DL 2646 FREQUENCY CONVERTER 1 1 1 DL 2108SAL SINGLE PHASE SUPPLY UNIT 1 1 1 DL 2109D33 TRUE RMS METER 2 2 2 2 DL CRON ELECTRONIC STOPCLOCK 1 1 1 1 DL 2100-3M FRAME 2 <t< td=""><td></td><td></td><td></td><td></td><td></td></t<> | | | | | |
| DL 2633 | | | | | |
| DL 2635 LOAD 1 | | | | | |
| DL 2637 STABILIZED POWER SUPPLY 1 1 DL 2640 EMI FILTER 1 1 DL 2643 SUPPORT WITH 3 SHUNTS 1 OHM 1 1 DL 2644 SUPPORT WITH 3 SHUNTS 0,1 OHM 1 1 DL 2646 FREQUENCY CONVERTER 1 1 DL 2108SAL SINGLE PHASE SUPPLY UNIT 1 1 DL 2109D33 TRUE RMS METER 2 2 2 DL CRON ELECTRONIC STOPCLOCK 1 1 1 DL 2100-3M FRAME 2 2 2 2 DL 1001-1 WORKING BENCH 1 1 1 1 DL 1155POW CONNECTING LEADS 1 1 1 1 Accessory: TOTAGE CABINET 1 1 1 1 Tor the Countries where the 3-phase mains supply is different from 380V: 1 1 1 1 | | | | 4 | |
| DL 2640 EMI FILTER 1 DL 2643 SUPPORT WITH 3 SHUNTS 1 OHM 1 DL 2644 SUPPORT WITH 3 SHUNTS 0,1 OHM 1 DL 2646 FREQUENCY CONVERTER 1 DL 2108SAL SINGLE PHASE SUPPLY UNIT 1 DL 2109D33 TRUE RMS METER 2 DL CRON ELECTRONIC STOPCLOCK 1 DL 2100-3M FRAME 2 DL 1001-1 WORKING BENCH 1 DL 1155POW CONNECTING LEADS 1 Accessory: 1 DL 2100TA STORAGE CABINET 1 For the Countries where the 3-phase mains supply is different from 380V: | | | _ | 1 | |
| DL 2643 SUPPORT WITH 3 SHUNTS 1 OHM 1 DL 2644 SUPPORT WITH 3 SHUNTS 0,1 OHM 1 DL 2646 FREQUENCY CONVERTER 1 DL 2108SAL SINGLE PHASE SUPPLY UNIT 1 DL 2109D33 TRUE RMS METER 2 DL CRON ELECTRONIC STOPCLOCK 1 DL 2100-3M FRAME 2 DL 1001-1 WORKING BENCH 1 DL 1155POW CONNECTING LEADS 1 Accessory: 1 DL 2100TA STORAGE CABINET 1 For the Countries where the 3-phase mains supply is different from 380V: 1 | | | _ | | |
| DL 2644 SUPPORT WITH 3 SHUNTS 0,1 OHM 1 1 DL 2646 FREQUENCY CONVERTER 1 1 DL 2108SAL SINGLE PHASE SUPPLY UNIT 1 1 DL 2109D33 TRUE RMS METER 2 2 2 DL CRON ELECTRONIC STOPCLOCK 1 1 1 DL 2100-3M FRAME 2 2 2 DL 1001-1 WORKING BENCH 1 1 1 1 DL 1155POW CONNECTING LEADS 1 1 1 1 Accessory: TORAGE CABINET 1 1 1 1 For the Countries where the 3-phase mains supply is different from 380V: 1 1 1 1 | | | | | |
| DL 2646 DL 2108SAL SINGLE PHASE SUPPLY UNIT DL 2109D33 TRUE RMS METER DL 2100-3M FRAME DL 1001-1 DL 1155POW DL 2100TA STORAGE CABINET For the Countries where the 3-phase mains supply is different from 380V: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | | | | | |
| DL 2108SAL DL 2109D33 SINGLE PHASE SUPPLY UNIT TRUE RMS METER 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 | | | 1 | 4 | _ |
| DL 2109D33 TRUE RMS METER 2 2 DL 2100-3M ELECTRONIC STOPCLOCK 1 1 DL 1001-1 WORKING BENCH 2 2 DL 1155POW CONNECTING LEADS 1 1 1 Accessory: 3 1 1 1 1 DL 2100TA STORAGE CABINET 1 1 1 1 1 1 For the Countries where the 3-phase mains supply is different from 380V: 1 1 1 1 1 | | | | | |
| DL CRON DL 2100-3M FRAME DL 1001-1 WORKING BENCH DL 1155POW CONNECTING LEADS Accessory: DL 2100TA STORAGE CABINET For the Countries where the 3-phase mains supply is different from 380V: | | | 2 | _ | |
| DL 2100-3M FRAME UL 1001-1 WORKING BENCH DL 1155POW CONNECTING LEADS Accessory: DL 2100TA STORAGE CABINET For the Countries where the 3-phase mains supply is different from 380V: | | | 2 | _ | |
| DL 1001-1 DL 1001-1 DL 1155POW CONNECTING LEADS Accessory: DL 2100TA STORAGE CABINET For the Countries where the 3-phase mains supply is different from 380V: | | | 2 | _ | |
| DL 1155POW CONNECTING LEADS Accessory: DL 2100TA STORAGE CABINET For the Countries where the 3-phase mains supply is different from 380V: | | | | _ | |
| Accessory: STORAGE CABINET For the Countries where the 3-phase mains supply is different from 380V: 1 1 1 1 | | | _ | _ | _ |
| DL 2100TA STORAGE CABINET For the Countries where the 3-phase mains supply is different from 380V: 1 1 1 | DL 1155POW | | 1 | 1 | 1 |
| For the Countries where the 3-phase mains supply is different from 380V: | DI 2400TA | • | | 4 | 4 |
| from 380V: | DL 21001A | | 1 | 1 | 1 |
| | | | | | |
| DL Z600111 THREE PHASE TRANSFORMER 1 1 1 1 | DI 2000TTI | | 1 | 4 | 4 |
| | DL 2600111 | THREE PHASE TRANSFURIVIER | 1 | 1 | 1 |





APPLICATIONS

Motor drives are used in a wide range of power values, from few watts up to many thousands of kilowatts, in applications ranging from high precision position control in robotics to variable speed drives for regulating the rate of flow in pumps.

In all drives where speed and position must be controlled, a power electronics converter is needed as interface between input power and motor.

Constant, or slightly variable according to load, speed drives use almost exclusively induction motors, thanks to their simple, robust and cheap construction, in addition to the fact that they do not need special maintenance. However, the multi-phase motors supplied at constant network voltage and frequency have a rigid relationship between supply frequency and speed.

Direct current motor drives are mainly used in applications requiring the control of the speed of the motor (DCA 205.1). In variable speed drives direct current machines are used everywhere; however, today, with the development of power electronics, induction motor drives are also widely used .

In these cases, the speed of the motor can be varied in three different ways: by varying the number of polar couples, by varying the slip speed (DCA 205.2), by varying the supply frequency (DCA 205.3).

LIST OF EXPERIMENTS

DCA 205.1 DC MOTOR DRIVE

- Single-quadrant drive with converter B2C
- Single-quadrant drive with converter B2C and armature voltage feedback
- Single-quadrant drive with converter B2C and armature voltage feedback with RI compensation
- Single-quadrant drive with converter B2C and tacho-voltage feedback
- Single-quadrant drive with converter B2C and tacho-voltage feedback with inner current loop
- Two-guadrant drive (I-IV) with converter B2C
- Two-quadrant drive (I-III) with converter (B2C)2I
- Two-quadrant drive (I-III) with converter (B2C)2I and tacho-voltage feedback with inner current loop
- Four-quadrant drive with converter (B2C)2I
- Four-quadrant drive with converter (B2C)2I and tacho-voltage feedback with inner current loop
- Single-quadrant drive with converter B6C
- Single-quadrant drive with converter B6C and tacho-voltage feedback with inner current loop

DCA 205.2 AC SLIP-RING MOTOR DRIVE

- Control of stator voltage with transformer
- Control of stator voltage with controller W3C
- Control of stator voltage and tacho-voltage feedback
- Rotor starter
- Rotor pulsed resistor
- Rotor pulsed resistor and tacho-voltage feedback
- Scherbius static drive
- Scherbius static drive and tacho-voltage feedback

DCA 205.3 AC SQUIRREL CAGE MOTOR DRIVE

- Preliminary investigation of the squirrel cage motor
- Six-pulse PAM
- Pulsed square-wave triggering
- Trapezoidal modulation
- Pulse width modulation (PWM)





- Voltage vector control (VVC)
- Motor magnetization for linear U/f characteristic
- Extra start magnetization
- IxR compensation
- Operation in standard converter setting
- Slip compensation
- Motor operation in star connection
- Brake chopper
- Speed control with tacho-voltage feedback

| Code | Description | DCA 205.1 | DCA 205.2 | DCA 205.3 | Total quantities |
|--------------------|--|-----------|-----------|-----------|------------------|
| DL 2603 | GROUP OF DIODES | | 1 | | 1 |
| DL 2605 | GROUP OF SCR | 2 | 1 | | 2 |
| DL 2609 | IGBT | _ | 1 | | 1 |
| DL 2613 | DC POWER SUPPLY | 1 | 1 | 1 | 1 |
| DL 2614 | VOLTAGE REFERENCE GENERATOR | 1 | 1 | 1 | 1 |
| DL 2615 | TRIGGER POINT LIMITER | 1 | 1 | _ | 1 |
| DL 2616 | TWO PULSE CONTROL UNIT | 1 | _ | | 1 |
| DL 2617 | SIX PULSE CONTROL UNIT | 1 | 1 | | 1 |
| DL 2619 | PWM/PFM/TPC CONTROL UNIT | _ | 1 | | 1 |
| DL 2620 | RUN-UP CONTROL UNIT | 1 | 1 | | 1 |
| DL 2622 | PID CONTROLLER | 1 | 1 | 1 | 1 |
| DL 2623 | ABSOLUTE VALUE GENERATOR | 1 | 1 | 1 | 1 |
| DL 2623 DL 2624 | ADAPTIVE PID CONTROLLER | 1 | | | 1 |
| DL 2625 | MATCHING AMPLIFIER | 1 | | | 1 |
| | | | 1 | | |
| DL 2626 DL 2628 | MAINS TRANSFORMER SUPER FAST FUSES | 1 1 | 1 2 | | 1 2 |
| DL 2628 DL 2630 | CURRENT TRANSFORMER | 1 | 2 | | 1 |
| | | 1 | | | |
| DL 2631 | TRIGGER PULSE SWITCH SWITCHING LOGIC | 1 | | | 1 1 |
| DL 2632 | | | | | |
| DL 2634 | VOLTAGE DIVIDER 20:1 | 1 | 4 | 4 | 1 |
| DL 2635 | LOAD | 1 | 1 | 1 | 1 |
| DL 2636 | SOCKETS WITH LAMPS | 1 | | | 1 |
| DL 2637 | STABILIZED POWER SUPPLY | 1 | _ | | 1 |
| DL 2643 | SUPPORT WITH 3 SHUNTS 1 OHM | 1 | 1 | | 1 |
| DL 2646 | FREQUENCY CONVERTER | | | 1 | 1 |
| DL 2648 | PWM CONTROL UNIT | | | 1 | 1 |
| DL 2655 | VARIABLE THREE PHASE TRANSFORMER | | 1 | | 1 |
| DL 2025DT | TACHOMETER | 1 | | | 1 |
| DL 2108SAL | SINGLE PHASE SUPPLY UNIT | | | 1 | 1 |
| DL 2108TAL-SW | THREE PHASE SUPPLY UNIT | | 1 | | 1 |
| DL 2109D33 | TRUE RMS METER | 2 | 2 | 1 | 2 |
| DL 2109T3PV | MOVING IRON VOLTMETER | | 1 | | 1 |
| DL 2109T2A5 | MOVING IRON AMMETER | 1 | 1 | | 1 |
| DL 10115A1 | SQUIRREL CAGE THREE PHASE MOTOR | | | 1 | 1 |
| DL 10120A1 | SLIP RING THREE PHASE MOTOR | | 1 | | 1 |
| DL 10120RA | ROTOR STARTER | 1 | 1 | | 1 |
| DL 10200A1 | SHUNT EXCITATION DC MOTOR | 1 | | | 1 |
| DL 10250A1 | SHUNT EXCITATION DC GENERATOR | 1 | | | 1 |
| DL 10300P | POWDER BRAKE | | 1 | 1 | 1 |
| DL 2006D | LOAD CELL | | 1 | 1 | 1 |
| DL 10300PAC | POWDER BRAKE CONTROL UNIT | | 1 | 1 | 1 |
| DL 10400 | BASE | 1 | 1 | 1 | 1 |
| DL 10410 | FLYWHEEL | | | 1 | 1 |
| DL 2100-3M | FRAME | 2 | 2 | 2 | 2 |
| DL 1001-1 | WORKING BENCH | 1 | 1 | 1 | 1 |
| DL 1155POW | CONNECTING LEADS | 1 | 1 | 1 | 1 |
| | Accessory: | | | | |
| DL 2100TA | STORAGE CABINET | 1 | 1 | 1 | 1 |
| | For the Countries where the 3-phase mains supply is different from 380V: | | | | |
| DL 2600TTI | THREE PHASE TRANSFORMER | 1 | 1 | 1 | 1 |





POWER ELECTRONICS TOTAL CONFIGURATION

The code **DCA TOT** covers all modules and experiment described in the previously configurations.

| Code | Description | 1.1 | 1.2 | 12.1 | 2.2 | 3.1 | 13.2 | 14.1 | 14.2 |)5.1 | 15.2 | 5.3 | то. |
|---------------|------------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|---------|
| Code | Description | DCA 201.1 | DCA 201.2 | DCA 202.1 | DCA 202.2 | DCA 203.1 | DCA 203.2 | DCA 204.1 | DCA 204.2 | DCA 205.1 | DCA 205.2 | DCA 205.3 | DCA TOT |
| DL 2601 | SELENIUM RECTIFIER | 1 | | | | | | | | | | | 1 |
| DL 2602 | SILICON DIODE | 1 | | | | 1 | 4 | | | | | | 4 |
| DL 2603 | GROUP OF DIODES | 1 | 1 | 1 | | | | | | | 1 | | 1 |
| DL 2604 | SCR | | 1 | | | | | | | | | | 1 |
| DL 2605 | GROUP OF SCR | | 1 | 1 | | | | | | 2 | 1 | | 2 |
| DL 2607 | TRIAC | | | 1 | | | | | | | | | 1 |
| DL 2608 | MOSFET | | | | | 1 | | | | | | | 1 |
| DL 2609 | IGBT | | | | | 1 | 2 | | | | 1 | | 2 |
| DL 2610 | GROUP OF IGBT | | | | | | | 1 | | | | | 1 |
| DL 2611 | BRIDGE THREE PHASE RECTIFIER | | | | | 1 | 1 | 1 | | | | | 1 |
| DL 2612 | SCR WITH TURN OFF CIRCUIT | | | | | 1 | | | | | | | 1 |
| DL 2613 | DC POWER SUPPLY | | 1 | 1 | | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |
| DL 2614 | VOLTAGE REFERENCE GENER. | | 1 | 1 | | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |
| DL 2615 | TRIGGER POINT LIMITER | | 1 | | | | | | | 1 | 1 | | 1 |
| DL 2616 | TWO PULSE CONTROL UNIT | | 1 | 1 | | | | | | 1 | | | 1 |
| DL 2617 | SIX PULSE CONTROL UNIT | | 1 | 1 | | | | | | 1 | 1 | | 1 |
| DL 2619 | PWM/PFM/TPC CONTROL UNIT | | | | | 1 | 1 | 1 | | | 1 | | 1 |
| DL 2620 | RUN-UP CONTROL UNIT | | | | | | | | | 1 | 1 | | 1 |
| DL 2622 | PID CONTROLLER | | | | | | | | | 1 | 1 | 1 | 1 |
| DL 2623 | ABSOLUTE VALUE GENERATOR | | | | | | | | | 1 | | | 1 |
| DL 2624 | ADAPTIVE PI CONTROLLER | | | | | | | | | 1 | | | 1 |
| DL 2625 | MATCHING AMPLIFIER | | | | | | | 1 | | 1 | | | 1 |
| DL 2626 | MAINS TRANSFORMER | 1 | 1 | 1 | 1 | 1 | 1 | 1 | | 1 | 1 | | 1 |
| DL 2627 | CAPACITORS | | | | | 1 | 1 | 1 | | | | | 1 |
| DL 2628 | SUPER FAST FUSES | 2 | 2 | 1 | | 1 | 1 | 1 | | 1 | 2 | | 2 |
| DL 2629 | SWITCHING TRANSFORMER | | | | | | 1 | | | | | | 1 |
| DL 2630 | CURRENT TRANSFORMER | | | | | 1 | | | | 1 | | | 1 |
| DL 2631 | TRIGGER PULSE SWITCH | | | | | | | | | 1 | | | 1 |
| DL 2632 | SWITCHING LOGIC | | | | | | | | | 1 | | | 1 |
| DL 2633 | FUNCTION GENERATOR | | | | | | | 1 | | | | | 1 |
| DL 2634 | VOLTAGE DIVIDER 20:1 | | | | | | | | | 1 | | | 1 |
| DL 2635 | LOAD | 1 | 1 | 1 | | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |
| DL 2636 | SOCKETS WITH LAMPS | | 1 | | 1 | | | | | 1 | | | 1 |
| DL 2637 | STABILIZED POWER SUPPLY | | 1 | | | | | 1 | | 1 | | | 1 |
| DL 2639 | PHASE CONTROL FAULT SIM. | | | | 1 | | | | | | | | 1 |
| DL 2640 | EMI FILTER | | | | | | 1 | 1 | | | | | 1 |
| DL 2643 | SUPPORT WITH 3 SHUNTS 1 OHM | 1 | 1 | 1 | | 1 | 1 | 1 | | 1 | 1 | | 1 |
| DL 2644 | SUPPORT WITH 3 SH. 0.1 OHM | | 1 | | | | 1 | 1 | | | | | 1 |
| DL 2646 | FREQUENCY CONVERTER | | | | | | | | 1 | | | 1 | 1 |
| DL 2648 | PWM CONTROL UNIT | | | | | | | | | | | 1 | 1 |
| DL 201SW | POWER EL. SW | | | | | | | | | | | | 1 |
| DL 2655 | VARIABLE THREE-PHASE TRANSF. | | | | | | | | | | 1 | | 1 |
| DL 12B12 | BATTERY STACK | | 1 | | | | | | | | | | 1 |
| DL 2025DT | TACHOMETER | | 1 | | | 1 | | | | 1 | | | 1 |
| DL 2108SAL | SINGLE PHASE SUPPLY UNIT | | | | | | | | 1 | | | 1 | 1 |
| DL 2108TAL-SW | THREE PHASE SUPPLY UNIT | | | | | | | | | | 1 | | 1 |
| DL 2109T26 | POWER METER | | | 1 | | | | | | | | | 1 |
| DL 2109D33 | TRUE RMS METER | 2 | 2 | 2 | | 2 | 2 | 2 | 2 | 2 | 2 | 1 | 2 |
| DL 2109T3PV | MOVING IRON VOLTMETER | 1 | 1 | 1 | | | | | | | 1 | | 1 |
| DL 2109T2A5 | MOVING IRON AMMETER | 1 | 1 | | | | | | | 1 | 1 | | 1 |
| DL 10115A1 | SQUIRREL CAGE THREE PHASE M. | | | | | | | | | | | 1 | 1 |
| DL 10120A1 | SLIP RING THREE PHASE MOTOR | | | | | | | | | | 1 | | 1 |
| DL 10120RA | ROTOR STARTER | | | | | | | | | | 1 | | 1 |





| DL 10200A1 | SHUNT EXCITATION DC MOTOR | | 1 | | | 1 | | | | 1 | | | 1 | ı |
|-------------|-----------------------------|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DL 10250A1 | SHUNT EXCITATION DC GENERA. | | 1 | | | | | | | 1 | | | 1 | ı |
| DL 10300P | POWDER BRAKE | | | | | | | | | | 1 | 1 | 1 | ı |
| DL 2006D | LOAD CELL | | | | | | | | | | 1 | 1 | 1 | ı |
| DL 10300PAC | POWDER BRAKE CONTROL UNIT | | | | | | | | | | 1 | 1 | 1 | l |
| DL 10400 | BASE | | 1 | | | 1 | | | | 1 | 1 | 1 | 1 | ı |
| DL 10410 | FLYWHEEL | | | | | | | | | | | 1 | 1 | |
| DL CRON | ELECTRONIC STOPCLOCK | | | | | | | | 1 | | | | 1 | ı |
| | PC (not included) | | | | | | | | | | | | 1 | ı |
| DL 2100-3M | FRAME | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | 2 | ı |
| DL 1001-1 | WORKING BENCH | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | ı |
| DL 1155POW | CONNECTING LEADS | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | ı |
| | Accessories: | | | | | | | | | | | | | ١ |
| DL 2100TA | STORAGE CABINET | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | ١ |
| DL 2600TTI | THREE PHASE TRANSFORMER | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | ı |